



TOWN OF LAUDERDALE-BY-THE-SEA

AGENDA ITEM REQUEST FORM

| | Tow | n Commissio | n | Commissioner Clottey | | | | | | |
|--------|--------------------------------------|---|---|--|--------------------------|--|--|--|--|--|
| | Departu | ient Submitting Requ | iest | | Dept Head's Sig | ınature | | | | |
| į | Commission Meeting Dates | Last date to turn in to Town Clerk's Office | Commission Meeting Dates | Last date to turn in to Town Clerk's Office | Commission Meeting Dates | Last date to turn in to Town Clerk's Office | | | | |
| | Nov 10, 2009 | Oct. 30 (5:00 p.m.) | ☐ Jan 26, 2010 | Jan 15 (5:00 p.m.) | March 23, 2010 | Mar 12 (5:00 p.m.) | | | | |
| | Dec 1, 2009 | Nov 20 (5:00 p.m.) | Feb 9,2010 | Jan 29 (5:00 p.m.) | April 13, 2010 | April 2 (5:00p.m.) | | | | |
| | Dec 8, 2009 | Nov 25 (5:00 p.m.) | Feb 23, 2010 | Feb 12 (5:00 p.m.) | April 27, 2010 | April 16 (5:00p.m.) | | | | |
| IJ | Jan 12, 2010 | Dec 31 (5:00 p.m.) | ☐ Mar 9, 2010 | Feb 26 (5:00p.m.) | May 11, 2010 | April 30 (5:00p.m.) | | | | |
| | TURE OF ENDA ITEM | | Presentation Report Consent Agenda Bids | Resolution Ordinance Public Hearing Old Business | ☐ M. g ☐ At | ew Business anager's Report torney's Report her | | | | |
| Impe | | | | ve the Town Engined to prevent through | | | | | | |
| STAI | FF RECOMME | ENDATION: N/A | | • | | | | | | |
| BOAL | RD/COMMIT | TEE RECOMMEN | DATION: N/A | | | | | | | |
| FISC | AL IMPACT A | .ND APPROPRIAT | TION OF FUNDS: | N/A | | | | | | |
| | Amount \$ Transfer of fund Bid | s required F | rom Acct # | nount represents matchin | ig funds | | | | | |
| Tr | nis iter noussion | n was | olefei 19 Comp verstane | rred at | the by | | | | | |
| Àb | DITIONAL | INFORMATION | le by comm | AT THE JANUA SSIZUER CLOTTE | 2RY 26,20 | 170 Cemmission | | | | |
| Town A | ttorney review re Yes (∑) | quired No | | · · · · · · · · · · · · · · · · · · · | Town Manag | er's Initials: | | | | |

John Olinzock

From:

James H. Barton [jbarton@chenandassociates.com]

To:

John Olinzock

Cc:

Peter Moore

Subject:

RE: Barrier Arm Study

Attachments:

Just a quick response (after thinking about this)

Survey: \$1,000

Design and Permitting: \$5,000

Road Construction: \$10,000 (no landscape or irrigation)

Sign and Striping: \$1,000

BULB-OUT OHLY ONE SIDE OF ROAD (NO APM)

Sent: Thu 21-Jan-10 1:10 PM

These may be a bit high but good for budgeting purposes.

We haven't moved forward to see if the County would allow this yet. Do you want us to move forward on that?

James

∩ • ±

.

5 • 0 0 0 • 0 0 +

10,000.00+

1,000+00+

17,000.00*

James Barton, P.E.

Senior Engineer


ESRI Authorized Trainer

Chen and Associates

500 Australian Avenue South, Suite 615

West Palm Beach, FL 33401

Phone: 561.746.6900



Disdusario de Ten. Common

March 8, 2010

Esther Colon Town Manager Lauderdale by the Sea 954 776 1857 Fax

Dear Ms. Colon,

For the past five months the residents of Imperial Lane have petitioned the town to take action with regard to the errant traffic problem on our street. The town engineer provided two options for barriers and since then it seems that we are at a standstill.

My neighbor Dr. Anthony Lamarca recently obtained quotes for a security arm himself which I have included in this fax. I would like to request that these be distributed to the mayor and the commissioners.

I am aware that a proposal to narrow the opening of the street and increase signage was put forward. I would like to know the result of this proposal.

Sincerely

Jeannigle Pearce Clark

271 Imperial Lane

Lauderdale by the Sea, FL 33308

<u>Jpclark6@aol.com</u> 954 478 9328 02/04/2010, 14:37

3056960461

L.A. ORNAMENTAL&RACK

PAGE 01/01

Arthur Velunza

L. A. Ornamental & Rack Corp 3708 North West 82nd Street

Miami, Florida 33147 Office: 305-696-0419 Fax: 305-696-0461

E-Mail: Arthur@LAOrnamental.com


Quote For Gate System—February 4, 2010

Anthony Lamarca Imperial Lane Lauderdale By The Sea 305-545-0993

Fax: 954-564-4326

| | | T | T |
|--|---|--|----------|
| Quantity | Description / Part Number | Price | Total |
| 2 | Viking B12 Commercial Barrier Operator with Battery Back Up 12' Wood Arm Included | 1,794.00 | 3,588.00 |
| 2 | Viking Green Load Spring for 12' Arms | 99.00 | 198.00 |
| 2 | Viking Solar Kit — Includes: (2) 40 Watt Solar Panels, (2) 35AH Batteries (1) Solar Charger, (1) Wire Harness | 1,475.00 | 2,950.00 |
| 4 | EMX LP Loop Detector with 4X8 Loop | 199.95 | 799.80 |
| | Installation for Equipment Mentioned Above | 1,600.00 | 1,600.00 |
| , | | | |
| | | | |
| And the second s | March 1997 | | |
| | | Sub-Total | 9135.80 |
| | | Tax 7% | 639.51 |
| | | Total | 9,775.31 |
| | | <u>. </u> | |

Received Time Feb. 10. 9:31 AM



1450 South Dixie Highway Building D Pompano Beach, FL 33060 Estimate

| Date | Estimate # |
|-----------|------------|
| 2/10/2010 | 311 |

Phon... 954-946-9499 Fax # 954-946-5233

E-mail Matrixgates 12@bellsouth.net

Name / Address
Anthony Lamarca

Project

| | | | | | | • |
|---------------------------------|--|--|-----|--------|----------------------|-------|
| Item | | Description | | Qty | Cost | Total |
| Custom Fa Powder op | Custom Fabricate and install All material to be powder coa | two swing barriers ted black, white, or bronze. | | 1 | 5,500.00 0.00 | |
| LA 400 D Solar 10 PB 1200 | SWING GATE KIT FOR DU 10 watt solar panels with brac REFLECTIVE PHOTOBEA | AL GATES WITH BATTERY BACK UP kets. A FOR SAFETY | | 1 1 | 0.00 0.00 0.09 | 0.00T |
| | optional barrier arms with sol | ar panels \$8500.00 | | | | |
| | | : | · | | | · |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | - 0 |
| | | | - 1 | - 1. | | |

All work to be done in a timely and professional manner.

Warranty is one year from completion of work. Warranty does not cover vandalism, abuse, misuse, accidents, unauthorized repairs and acts of gods.

Terms are 50% deposit and 50% upon completion.

This quote does not include permit fees.

If quoting gate operators 110 vac to the operator is the owners responsibility.

 Subtotal
 \$5,500.00

 Sales Tax (6.0%)
 \$330.00

 Total
 \$5,830.00


Signature

Į d

964-946-5233

Matrix Gate Systems inc.

50€:60 01 01 dA





K E L

HP LASERJET FAX

Mar 08 2010 1:15AM

Broward County Traffic Engineering

Traffic Study

Nu-Metrics Traffic Analyzer Study Computer Generated Summary Report City: LAUDERDALE BY THE SEA

Street: IMPERIAL LA NEAR THOMAS WAY

A study of vehicle traffic was conducted with HI-STAR unit number 1297. The study was done in the EB lane on IMPERIAL LA NEAR THOMAS WAY in LAUDERDALE BY THE SEA, FL in BROWARD county. The study began on 02/09/2010 at 11:00 PM and concluded on 02/10/2010 at 11:00 PM, lasting a total of 24 hours. Data was recorded in 60 minute time periods. The total recorded volume of traffic showed 394 vehicles passed through the location with a peak volume of 156 on 02/10/2010 at 04:00 PM and a minimum volume of 0 on 02/10/2010 at 02:00 AM. The AADT Count for this study was 394.

SPEED

Chart 1 lists the values of the speed bins and the total traffic volume for each bin.

| | Chart 1 | | | | | | | | | | | | | | |
|---|---------|----|-----|----|----|----|----|----|----|----|----|----|----|----|----|
| 1 | 0 | 10 | 15 | 20 | 25 | 30 | 35 | 40 | 45 | 50 | 55 | 60 | 65 | 70 | 75 |
| | to | to | to | to | to | to | to | to | to | to | to | to | to | to | > |
| | 9 | 14 | 19 | 24 | 29 | 34 | 39 | 44 | 49 | 54 | 59 | 64 | 69 | 74 | |
| | 0 | 63 | 125 | 56 | 65 | 15 | 13 | 12 | 17 | 10 | 5 | 1 | 3 | 1 | 0 |

At least half of the vehicles were traveling in the 20 - 24 mph range or a lower speed. The average speed for all classified vehicles was 25 mph with 51.3 percent exceeding the posted speed of 20 mph. The HI-STAR found 2.59 percent of the total vehicles were traveling in excess of 55 mph. The mode speed for this traffic study was 15 mph and the 85th percentile was 36.58 mph.

CLASSIFICATION

Chart 2 lists the values of the eight classification bins and the total traffic volume accumulated for each bin.

| | | | Ch | art 2 | | | |
|----------|----|----------|----------|----------|----------|----------|----|
| 0 | 21 | 28 | 40 | 50 | 60 | 70 | 80 |
| to 20 | to | to 39 | to 49 | to 59 | to 69 | to 79 | > |
| 333 | 9 | 19 | 7 | 8 | 3 | 2 | 5 |

Most of the vehicles classified during the study were Passenger Cars. The number of Passenger Cars in the study was 342 which represents 88.60 percent of the total classified vehicles. The number of Small Trucks in the study was 19 which represents 4.90 percent of the total classified vehicles. The number of Trucks/Buses in the study was 7 which represents 1.80 percent of the total classified vehicles. The number of Tractor Trailers in the study was 18 which represents 4.70 percent of the total classified vehicles.

HEADWAY

During the peak time period, on 02/10/2010 at 04:00 PM the average headway between the vehicles was 22.93 seconds. The slowest traffic period was on 02/10/2010 at 02:00 AM. During this slowest period, the average headway was 3600.0 seconds.

WEATHER

The roadway surface temperature over the period of the study varied between 62 and 97 degrees Fahrenheit. The HI-STAR determined that the roadway surface was Dry 100.00 percent of the time.

Time/Speed Report

| HI-Star ID: 1297 Street: IMPERIAL LA NE 당성인계속을 WAY County: BROWARD | | Begin: 02/09/2010 11:00 Lane: EB Oper: CP Posted: 20 AADT Factor: 1 | | | | 00 P | PM End: 02/10/2010 11:00 PM Hours: 24:00 Period: 60 Raw Count: 394 AADT Count: 394 | | | | | 1 | | | | |
|---|--------------|---|----------------|----------------|----------------|----------------|--|----------------|------------------|----------------|------------------|----------------|----------------|--------------------|---------|-----------------|
| NC97 - mph | 0 to 9 | 10 to 14 | 15 to 19 | 20 to 24 | 25 to 29 | 30 to 34 | 35 to 39 | 40 to 44 | 45 to 49 | 50 to 54 | 55 to 59 | 60 to 64 | 65 to 69 | 70 to 74 | 75 > | Total |
| 02/09/2010 | | | | - | | | | | | | | | | | | |
| [11:00 PM-12:00 AM] | <u>0</u> | <u></u> 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 - | 0 | 0 | 0 - | 0 - | 0 - | 0 | 1 |
| Daily Totals: | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| 02/10/2010 | | | | | | | | | | | | | | | | |
| [12:00 AM-01:00 AM] | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [01:00 AM-02:00 AM] | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| [02:00 AM-03:00 AM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [03:00 AM-04:00 AM] | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [04:00 AM-05:00 AM] | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [05:00 AM-06:00 AM] | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| [06:00 AM-07:00 AM] | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 |
| [07:00 AM-08:00 AM] | 0 | 2 | 9 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 17 |
| [08:00 AM-09:00 AM] | 0 | 5 | 7 | 6 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 21 |
| [09:00 AM-10:00 AM] | 0 | 9 | 11 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 23 |
| [10:00 AM-11:00 AM] | 0 | 6 | 8 | 9 | 2 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 26 |
| [11:00 AM-12:00 PM] | 0 | 1 | 10 | 3 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 15 |
| [12:00 PM-01:00 PM] | 0 | 16 | 10 | 3 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 31 |
| [01:00 PM-02:00 PM] | 0 | 7 | 9 | 3 | 4 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 24 |
| [02:00 PM-03:00 PM] | 0 | 6 | 14 | 10 | 3 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 34 |
| [03:00 PM-04:00 PM] | 0 | 6 | 16 | 2 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 28 |
| [04:00 PM-05:00 PM] | 0 | 2 | 27 | 7 | 47 | 13 | 12 | 12 | 17 | 9 | 5 | 1 | 3 | 1 | 0 | 156 |
| [05:00 PM-06:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [06:00 PM-07:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [07:00 PM-08:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [08:00 PM-09:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [09:00 PM-10:00 PM] | 0 | 0 - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [10:00 PM-11:00 PM] | 0 | 0 | 0 | <u>0</u> 56 | 0 65 | <u>0</u> | 0 | <u>0</u> | $\frac{0}{17}$ - | 0 - | _ 0 - | 0 1 | 0 | - <mark>0</mark> - | 0 | <u>0</u> 385 |
| 1 | 0 | 63 | 124 | 50 | 05 | 10 | 13 | 12 | ,, | 10 | Ü | | | • | _ | |
| Daily Totals: | 0 | 63 | 124 | 56 | 65 | 15 | 13 | 12 | 17 | 10 | 5 | 1 | 3 | 1 | 0 | 385 |
| Report Totals: | 0 | 63 | 125 | 56 | 65 | 15 | 13 | 12 | 17 | 10 | 5 | 1 | 3 | 1 | 0 | 386 |
| Report Percentages: | 0.00% 16 | 32 3.32% | | 16 51%. | | .89% | | .11% | | 1 .59% | .30% 0 | 0. 26%. | .78% 0. | 0. 26% | 00% | |

Page 1 of 1 02/11/2010

Date/Time/Volume/Average Speed/Temperature Report

Begin: 02/09/2010 11:00 PM HI-Star ID: 1844 End: 02/10/2010 11:00 PM Hours: 24:00

Street: IMPERIAL LA NEAR THOMAS Wane: WB

Period: 60 Oper: CP Posted: 20 Raw Count: 371

County: BROWARD AADT Factor: 1 AADT Count: 371

| County: Citation in the | | | | |
|-------------------------|-------|-----------|------|---------|
| | | | | |
| NC97 | Count | Avg Speed | Temp | Wet/Dry |
| 02/09/2010 | | | • | |
| [11:00 PM-12:00 AM] | 2 | 18 mph | 72 F | Dry |
| 02/10/2010 | | | | |
| [12:00 AM-01:00 AM] | 1 | 18 mph | 72 F | Dry |
| [01:00 AM-02:00 AM] | 0 | 0 mph | 70 F | Dry |
| [02:00 AM-03:00 AM] | 0 | 0 mph | 68 F | Dry |
| [03:00 AM-04:00 AM] | 2 | 22 mph | 66 F | Dry |
| [04:00 AM-05:00 AM] | 1 | 23 mph | 66 F | Dry |
| [05:00 AM-06:00 AM] | 0 | 0 mph | 64 F | Dry |
| [06:00 AM-07:00 AM] | 1 | 33 mph | 64 F | Dry |
| [07:00 AM-08:00 AM] | 6 | 22 mph | 64 F | Dry |
| [08:00 AM-09:00 AM] | 12 | 19 mph | 64 F | Dry |
| [09:00 AM-10:00 AM] | 18 | 24 mph | 70 F | Dry |
| [10:00 AM-11:00 AM] | 19 | 21 mph | 78 F | Dry |
| [11:00 AM-12:00 PM] | 20 | 24 mph | 85 F | Dry |
| [12:00 PM-01:00 PM] | 22 | 21 mph | 91 F | Dry |
| [01:00 PM-02:00 PM] | 15 | 23 mph | 93 F | Dry |
| [02:00 PM-03:00 PM] | 28 | 25 mph | 93 F | Dry |
| [03:00 PM-04:00 PM] | 21 | 26 mph | 91 F | Dry |
| [04:00 PM-05:00 PM] | 203 | 43 mph | 83 F | Dry |
| [05:00 PM-06:00 PM] | 0 | 0 mph | 82 F | Dry |
| [06:00 PM-07:00 PM] | 0 | 0 mph | 78 F | Dry |
| [07:00 PM-08:00 PM] | 0 | 0 mph | 76 F | Dry |
| [08:00 PM-09:00 PM] | 0 | 0 mph | 70 F | Dry |
| [09:00 PM-10:00 PM] | 0 | 0 mph | 66 F | Dry |
| [10:00 PM-11:00 PM] | 0 | 0 mph | 62 F | Dry |

Nu-Metrics Traffic Analyzer Study Computer Generated Summary Report City: LAUDERDALE BY THE SEA

Street: IMPERIAL LA NEAR THOMAS WAY

A study of vehicle traffic was conducted with HI-STAR unit number 1844. The study was done in the WB lane on IMPERIAL LA NEAR THOMAS WAY in LAUDERDALE BY THE SEA, FL in BROWARD county. The study began on 02/09/2010 at 11:00 PM and concluded on 02/10/2010 at 11:00 PM, lasting a total of 24 hours. Data was recorded in 60 minute time periods. The total recorded volume of traffic showed 371 vehicles passed through the location with a peak volume of 203 on 02/10/2010 at 04:00 PM and a minimum volume of 0 on 02/10/2010 at 01:00 AM. The AADT Count for this study was 371.

SPEED

Chart 1 lists the values of the speed bins and the total traffic volume for each bin.

| Chart 1 | | | | | | | | | | | | | | |
|---------|----|----|----|----|----|----|----|----|----|----|-----|----|----|----|
| 0 | 10 | 15 | 20 | 25 | 30 | 35 | 40 | 45 | 50 | 55 | 60 | 65 | 70 | 75 |
| to | to | to | to | to | to | to | to | to | to | to | to | to | to | > |
| 9 | 14 | 19 | 24 | 29 | 34 | 39 | 44 | 49 | 54 | 59 | 64_ | 69 | 74 | |
| 0 | 7 | 54 | 60 | 66 | 58 | 42 | 4 | 1 | 12 | 18 | 27 | 17 | 0 | 2 |

At least half of the vehicles were traveling in the 25 - 29 mph range or a lower speed. The average speed for all classified vehicles was 34 mph with 83.4 percent exceeding the posted speed of 20 mph. The HI-STAR found 17.3 percent of the total vehicles were traveling in excess of 55 mph. The mode speed for this traffic study was 25 mph and the 85th percentile was 57.44 mph.

CLASSIFICATION

Chart 2 lists the values of the eight classification bins and the total traffic volume accumulated for each bin.

| | Chart 2 | | | | | | | | | | | | |
|-----|---------|----|----|----|----|----|----|--|--|--|--|--|--|
| 0 | 21 | 28 | 40 | 50 | 60 | 70 | 80 | | | | | | |
| to | to | to | to | to | to | to | > | | | | | | |
| 20 | 27 | 39 | 49 | 59 | 69 | 79 | | | | | | | |
| 301 | 18 | 14 | 9 | 10 | 4 | 2 | 10 | | | | | | |

Most of the vehicles classified during the study were Passenger Cars. The number of Passenger Cars in the study was 319 which represents 86.70 percent of the total classified vehicles. The number of Small Trucks in the study was 14 which represents 3.80 percent of the total classified vehicles. The number of Trucks/Buses in the study was 9 which represents 2.40 percent of the total classified vehicles. The number of Tractor Trailers in the study was 26 which represents 7.10 percent of the total classified vehicles.

HEADWAY

During the peak time period, on 02/10/2010 at 04:00 PM the average headway between the vehicles was 17.65 seconds. The slowest traffic period was on 02/10/2010 at 01:00 AM. During this slowest period, the average headway was 3600.0 seconds.

WEATHER

The roadway surface temperature over the period of the study varied between 62 and 93 degrees Fahrenheit. The HI-STAR determined that the roadway surface was Dry 100.00 percent of the time.

Time/Speed Report

| HI-Star ID: 1844 Street: IMPERIAL LA N ട്രൂപ്പ് WAY | EAR | | Lan Ope Pos | e: W er: C ted: | /B P 20 | | 11:0 | 00 PI | И | Ho Pe Ra | urs: riod: w Co | 24:0 60 ount: | | | 19 O | Л |
|---|--------------|----------------|-------------------|-----------------------|----------------|----------------|----------------|----------------|----------------|----------------|-----------------------|---------------------|----------------|----------------|---------|-----------------|
| County: BROWARD | | | AAL |) | actor | . 1 | | | | | | | | | | |
| NC97 - mph | 0 to 9 | 10 to 14 | 15 to 19 | 20 to 24 | 25 to 29 | 30 to 34 | 35 to 39 | 40 to 44 | 45 to 49 | 50 to 54 | 55 to 59 | 60 to 64 | 65 to 69 | 70 to 74 | 75 > | Total |
| 02/09/2010 | | | | | | | | | | | | | • | | | |
| [11:00 PM-12:00 AM] | 0 | 0 | 2 | <u>0</u> | 0 | 0 | 0 | 0 | <u></u> 0 - | 0 | 0 | 0 | 0 - | 0 | 0 | 2 |
| Daily Totals: | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| 02/10/2010 | | | | | | | | | | | | | | | | |
| [12:00 AM-01:00 AM] | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [01:00 AM-02:00 AM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [02:00 AM-03:00 AM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [03:00 AM-04:00 AM] | 0 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 |
| [04:00 AM-05:00 AM] | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [05:00 AM-06:00 AM] | 0 | Q | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [06:00 AM-07:00 AM] | 0 | O | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| [07:00 AM-08:00 AM] | 0 | 0 | 2 | 2 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6 |
| [08:00 AM-09:00 AM] | 0 | 0 | 9 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 12 |
| [09:00 AM-10:00 AM] | 0 | 1 | 8 | 5 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 18 |
| [10:00 AM-11:00 AM] | 0 | 3 | 6 | 7 | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 19 |
| [11:00 AM-12:00 PM] | 0 | 0 | 6 | 10 | 2 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 20 |
| [12:00 PM-01:00 PM] | 0 | 0 | 10 | 6 | 3 | 1 | 0 | O | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 20 |
| [01:00 PM-02:00 PM] | 0 | 1 | 6 | 5 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 14 |
| [02:00 PM-03:00 PM] | 0 | 1 | 3 | 11 | 11 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 28 |
| [03:00 PM-04:00 PM] | 0 | 1 | 0 | 8 | 9 | 2 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 21 |
| [04:00 PM-05:00 PM] | 0 | 0 | 1 | 0 | 34 | 51 | 41 | 2 | 1 | 12 | 17 | 27 | 16 | 0 | 1 | 203 |
| [05:00 PM-06:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [06:00 PM-07:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [07:00 PM-08:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| [08:00 PM-09:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | _ |
| [09:00 PM-10:00 PM] | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 . | 0 | 0 |
| [10:00 PM-11:00 PM] | 0 - | <u>0</u> 7 | 52 | 60 | 0 66 | 0 58 | 0 - | 0 - | | 0 12 | <u>0</u> 18 | 27 | 17 | _0 _ | 2 | <u>0</u> 366 |
| Daily Totals: | 0 | 7. | 52 | 60 | 66 | 58 | 42 | 4 | 1 | 12 | 18 | 27 | 17 | 0 | 2 | 366 |
| Report Totals: | 0 | 7 | 54 | 60 | 66 | 58 | 42 | 4 | 1 | 12 | 18 | 27 | 17 | 0 | 2 | 368 |
| Report Percentages: | 0.00% 1 | | | 17 5.30% | | 11 5.76% | .41% 5 1 | 0 %90. | .27% 3 | 4 .26% | .89% 7 | . 4 .34% | 1.62% 0 | 0 00%. | .54% | ı |

Date/Time/Volume/Average Speed/Temperature Report

HI-Star ID: 1297

Begin: 02/09/2010 11:00 PM

End: 02/10/2010 11:00 PM

Street: IMPERIAL LA NEAR THOMAS Wane: EB

Hours: 24:00

State: FL

Oper: CP

Period: 60


County: BROWARD

Posted: 20 AADT Factor: 1 Raw Count: 394 AADT Count: 394

| County: BROWARD | AADIFa | actor: 1 | AAD I Count. 394 | | | |
|---------------------|--------|------------------|------------------|---------------------------------------|--|--|
| | | | | | | |
| NC97 | Count | Avg Speed | Temp | Wet/Dry | | |
| 02/09/2010 | | | | | | |
| [11:00 PM-12:00 AM] | 1 | 18 mph | 74 F | Dry | | |
| 02/10/2010 | | | 70.5 | D=. | | |
| [12:00 AM-01:00 AM] | 1 | 18 mph | 72 F | Dry | | |
| [01:00 AM-02:00 AM] | 2 | 20 mph | 70 F | Dry | | |
| [02:00 AM-03:00 AM] | 0 | 0 mph | 68 F | Dry | | |
| [03:00 AM-04:00 AM] | 1 | 23 mph | 66 F | Dry | | |
| [04:00 AM-05:00 AM] | 1 | 13 mph | 66 F | Dry | | |
| [05:00 AM-06:00 AM] | 2 | 18 mph | 64 F | Dry | | |
| [06:00 AM-07:00 AM] | 3 | 18 mph | 64 F 64 F | Dry Dry | | |
| [07:00 AM-08:00 AM] | 17 | 19 mph | 62 F | Dry | | |
| [08:00 AM-09:00 AM] | 21 | 19 mph | | · · · · · · · · · · · · · · · · · · · | | |
| [09:00 AM-10:00 AM] | 25 | 16 mph | 70 F | Dry Dry | | |
| [10:00 AM-11:00 AM] | 27 | 20 mph | 80 F 87 F | Dry | | |
| [11:00 AM-12:00 PM] | 17 | 19 mph | 93 F | Dry | | |
| [12:00 PM-01:00 PM] | 34 | 16 mph | 93 F 97 F | Dry | | |
| [01:00 PM-02:00 PM] | 24 | 19 mph | 97 F | Dry | | |
| [02:00 PM-03:00 PM] | 34 | 19 mph 18 mph | 93 F | Dry | | |
| [03:00 PM-04:00 PM] | 28 | 34 mph | 82 F | Dry | | |
| [04:00 PM-05:00 PM] | 156 | 0 mph | 82 F | Dry | | |
| [05:00 PM-06:00 PM] | 0 | 0 mph | 76 F | Dry | | |
| [06:00 PM-07:00 PM] | 0 | 0 mph | 74 F | Dry | | |
| [07:00 PM-08:00 PM] | 0 | 0 mph | 68 F | Dry | | |
| [08:00 PM-09:00 PM] | 0 | 0 mph | 66 F | Dry | | |
| [09:00 PM-10:00 PM] | 0 | 0 mph | 62 F | Dry | | |
| [10:00 PM-11:00 PM] | . 0 | o mpn | 021 | 3.19 | | |







BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT DIRECTORIES MEETINGS

- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Traffic Calming Measures - Choker

Description:

- curb extensions at midblock or intersection corners that narrow a street by extending the sidewalk or widening the planting strip
- can leave the cross section with two narrow lanes or with a single lane
- at midblock, sometimes called parallel chokers, angled chokers, twisted chokers, angle points, pinch points, or midblock narrowings
- at intersections, sometimes called neckdowns, bulbouts, knuckles, or corner bulges
- if marked as a crosswalk, they are also called safe crosses






Transoft

leading CAD software for transportation engineers

Applications:

- · local and collector streets
- pedestrian crossings
- · main roads through small communities
- work well with speed humps, speed tables, raised intersections, textured crosswalks, curb radius reductions, and raised median islands





as summered suns Federal High Administrat



1099 14th Street, NV West Washington, 20005-3438 L Phone: 202-289-Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE | RAISED INTERSI CLOSURE | NEIGHI TRAFFIC CIRCLE | ' CHOKER | CENTEI NARROWIN








Design/Installation Issues:

- some applications use an island which allows drainage and bicyclists to continue between the choker and the original curb line
- typically designed to narrow road to 20 feet for two-way traffic; typically avoid the use



- of widths between 13 and 17 feet
- adequate drainage is a key consideration
- provides opportunity for landscaping
- vertical delineators, bollards or object markers are often used to make visible to snowplow operators

Potential Impacts:

- · can impact parking and driveway access
- reduces pedestrian crossing width and increases visibility of pedestrian
- speeds have typically been reduced on average by 4 percent for twolane chokers and 14 percent for one lane chokers
- minor decrease in traffic for two-lane and 20 percent reduction for onelane chokers
- · collision data not available
- bicyclists prefer not to have the travelway narrowed into path of motor vehicles


Emergency Response Issues:

 preferred by many fire department/emergency response agencies to most other traffic calming measures

Other/Special Considerations:

• one-lane chokers rely on regulatory signs and driver courtesy to work

Typical Cost:



• approximately \$7,000 to \$10,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org

Sent: Thu 21-Jan-10 1:10 PM

John Olinzock

From:

James H. Barton [jbarton@chenandassociates.com]

To:

John Olinzock

Cc:

Peter Moore

Subject:

RE: Barrier Arm Study

Attachments:

Just a quick response (after thinking about this)

Survey: \$1,000

Design and Permitting: \$5,000

Road Construction: \$10,000 (no landscape or irrigation)

Sign and Striping: \$1,000

These may be a bit high but good for budgeting purposes.

We haven't moved forward to see if the County would allow this yet. Do you want us to move forward on that?

James

James Barton, P.E.

Senior Engineer

ESRI Authorized Trainer

Chen and Associates

500 Australian Avenue South, Suite 615

West Palm Beach, FL 33401

Phone: 561.746.6900

Mobile: 954.914.8488

Fax: 561.746.8333

Website: www.chenandassociates.com

CE News Best Places to Work 2008 - "Highest Ranked Civil Engineering Firm in South Florida"

South Florida Business Journal 2007 - "Best of Places to Work South Florida"

From: John Olinzock [mailto:johno@lauderdalebythesea-fl.gov]

Sent: Thursday, January 21, 2010 11:41 AM

To: James H. Barton

Subject: FW: Barrier Arm Study

Need ASAP.

John E. Olinzock

Assistant Town Manager

Town of Lauderdale By-The-Sea

4501 Ocean Drive

Lauderdale By-The-Sea, FL 33308-3610

954-776-0576

From: John Olinzock

Sent: Wed 20-Jan-10 3:24 PM

To: James H. Barton

Subject: RE: Barrier Arm Study

James, It is back on the next agenda. To do just the bulb-out or chicane, \$10,000.00 plus what other items in your spreadsheet? No gate. Send a revised sheet. Call me if you have questions. Cell. John E. Olinzock Assistant Town Manager Town of Lauderdale By-The-Sea 4501 Ocean Drive Lauderdale By-The-Sea, FL 33308-3610 954-776-0576 From: James H. Barton [mailto:jbarton@chenandassociates.com] Sent: Tue 08-Dec-09 2:44 PM To: Esther Colon Cc: John Olinzock Subject: Barrier Arm Study Esther,

Please note that we need more information to get a better cost estimate. Let me know if this is readily understandable or if you need additional information.

Thanks for the opportunity.

James

James Barton, P.E.

Senior Engineer

ESRI Authorized Trainer

Chen and Associates

500 Australian Avenue South, Suite 615

West Palm Beach, FL 33401

Phone: 561.746.6900


Mobile: 954.914.8488

Fax: 561.746.8333

Website: www.chenandassociates.com

CE News Best Places to Work 2008 - "Highest Ranked Civil Engineering Firm in South Florida"

South Florida Business Journal 2007 - "Best of Places to Work South Florida"



Esther Colon Town Manager Town of Lauderdale By the Sea

Subject: Traffic Barrier on Imperial Lane

The Town requested Chen and Associates to investigate the possibility of installing a traffic arm barrier on Imperial Lane. It was reported that many vehicles mistakenly go down Imperial Lane thinking it has an outlet, only to find it is a dead end.

Background



Imperial lane is at the south end of the Town. It connects to A1A at a signaled intersection at the east end. The west end is a cul-de-sac. The only exit is a turn south onto Thomas Way. Vehicles trying to get off A1A turn at the light thinking there is an outlet. The vehicles do not see the Dead End sign at the intersection of Thomas Way and continue down Imperial Lane. These vehicles cannot turn around as the street is 21ft in width (50ft Right of Way). They must go to the end of the street, 1500 ft, make a u-turn at the cul-de-sac and typically exit the street at an elevated speed.

A field visit confirmed that the intersection at Thomas Way is much wider than the rest of the road and the Dead End sign can be is easily missed by vehicles not familiar with the area.

Traffic Barrier Arm

Chen and Associates did some research on the possibility of installing a mast arm in the roadway on Imperial Lane. There were a list of issued that would need to be addressed before a proposal could be drafted. These include:


- Would another type of traffic calming method be acceptable
- Would there be a guard gate
- Would there be an arm barrier for entry only or for exit
- Would the residents want solar or electric power
- Would residents buzz in or would the arm barrier open to all vehicles
- How would visitors and emergency vehicles buzz in
- How many vehicles would wait in the queue
- Where would vehicles turn around if they had to leave
- Would there be landscape improvements

In order to get a basis for looking at costs, some locally available models were investigated. A list of contractors that have installed these before was requested from a local supplier. Some basic assumptions were made:


- Barrier arm installed at the intersection of Thomas Way and Imperial Lane. This would provide vehicles who don't want to enter sufficient room to turn around. If the arm is installed further down the road, the road must be widened to facilitate vehicle turnaround.
- No guard gate
- Entry barrier arm only
- The barrier arm will be 15' wide counterbalanced arm mounted on a pedestal base.
- It would be powered by electric supply
- It would require a concrete foundation,
- It would require installation of loop sensors to automatically open for any vehicle entering the street.

Site Plan Options

Option 1 has a barrier arm installed with the current road configuration. Due to the width of the road, the only location for the barrier arm is next to the driveway of resident at 215 Imperial. The arm in this location may not be effective due to the road width.



Option 2 has a modified road layout to partially close the intersection. This will naturally send vehicles around the corner that should not be going down Imperial, and will narrow the passage for the mast arm. This will serve as a double barrier for vehicles mistakenly going down the street.



For purposes of budgeting, a cost estimate has been made for design and installation. These values are based on the above assumptions and do not constitute a final quote. There are unknown variables. This cost estimate is provided as a guideline only.


| | Option 1 | Option 2 |
|-----------------------------|----------|----------|
| Structural Design | \$1,500 | \$1,500 |
| Electrical Design | \$2,500 | \$2,500 |
| Survey | \$1,500 | \$1,500 |
| Plans and Permits | \$7,000 | \$7,000 |
| Construction | \$15,000 | \$25,000 |
| Construction Certifications | \$2,500 | \$2,500 |
| Total Cost Estimate | \$30,000 | \$40,000 |

This cost estimate is for discussion purposes only. There would have to be discussions with residents to finalize design elements before a proposal could be finalized.

Please review this information and call me if you have any questions.

Respectfully submitted

CHEN AND ASSOCIATES James Barton P.E.








BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT DIRECTORIES MEETINGS

- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT



A series of fact sheets providing an overview of several traffic calming measures are available from this Web page. A photograph of a typical application as well as a planview sketch adapted from the Boulder, Colorado *Neighborhood Traffic Mitigation Program Toolkit* are included within each fact sheet.

Four types of measures are summarized:

- Vertical deflections, horizontal shifts, and roadway narrowings are intended to reduce speed and enhance the street environment for nonmotorists.
- Closures (diagonal diverters, half closures, full closures, and median barriers) are intended to reduce cut-through traffic by obstructing traffic movements in one or more directions.



For each traffic measure, inforr been compiled variety of sourc

Traffic Calming Practice (ITE/F

Canadian Guid Neighbourhood Calming (TAC and CITE

Traffic Calming Noyes & Assoc

Guidelines for t and Applicatior Humps (ITE)



Federal h Adminis



1099 14th Stre 300 V




















Washingt 20005-34 Phone: 202-Fax: 202-2 Send comr website@


The information provided on these fact sheets has been obtained from the research and experience of transportation engineering and planning professionals. The information is intended for informational purposes only and does not include ITE or FHWA recommendations on the best course of action.

Photos of traffic calming devices were provided by Reid Ewing.

CENTER ISLAND NARROWING

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA
Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org





BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT

T DIRECTORIES MEET

- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
-
- > LOGIN
- > LOGOUT > PAY DUES
- > CHECKOUT

Description:

Circle

• raised islands, placed in intersections, around which traffic circulates

Traffic Calming Measures - Neighborhood Traffic

- motorists yield to motorists already in the intersection
- require drivers to slow to a speed that allows them to comfortably maneuver around them
- · sometimes called intersection islands
- · different from roundabouts

Applications:

- intersections of local or collector streets
- one lane each direction entering intersection
- not typically used at intersections with high volume of large trucks and buses turning left






Transoft

leading CAD software for transportation engineers







Design/Installation Issues:

- typically circular in shape, though not always
- usually landscaped in their center islands, though not always
- often controlled by YIELD signs on all approaches, but many different signage approaches








Federal High Administrat



1099 14th Street, NV West Washington, 20005-3538 L Phone: 202-289-Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE | RAISED INTERSI CLOSURE | NEIGHI TRAFFIC CIRCLE | I CHOKER | CENTEI NARROWIN



have been used key design features are the offset distance (distance between projection of street curb and center island), lane width for circling the circle, the circle diameter, and height of mountable outer ring for large vehicles such as school buses and trash trucks

Potential Impacts:

- · no effect on access
- reduction in midblock speed of about 10 percent; area of influence tends to be a couple hundred feet upstream and downstream of intersection
- only minimal diversion of traffic
- intersection collisions have been reduced on average by 70 percent and overall collisions by 28 percent
- can result in bicycle/auto conflicts at intersections because of narrowed travel lane

Emergency Response Issues:

- emergency vehicles typically slow to approximately 13 mph; approximate delay of between 5 and 8 seconds per circle for fire trucks
- fire trucks can maneuver around traffic circles at slow speeds provided vehicles are not parked near the circle

Other/Special Considerations:


- large vehicles may need to turn left in front of the circle (which could be unsafe at higher volumes); legislation may be required to legally permit this movement
- quality of landscaping and its maintenance are key issues
- landscaping needs to be designed to allow adequate sight distance
- care must be taken to avoid routing vehicles through unmarked crosswalks on side-street approach

Typical Cost:

approximately \$3,500 to \$15,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org





EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT

> HOME

> JOIN ITE TODAY!

- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT


Description:

- · a series of narrowings or curb extensions that alternate from one side of the street to the other forming S-shaped curves
- also called deviations, serpentines, reversing curves, twists, and staggerings

Traffic Calming Measures - Chicane

Applications:

- appropriate for midblock locations only
- most effective with equivalent volumes on both approaches
- typically, is a series of at least three curb extensions
- can use on-street parking to create chicane



Design/Installation Issues:

- unless well-designed, chicanes may still permit speeding by drivers cutting straight paths across the center line
- European manuals recommend shifts in alignment of at least one lane width, deflection angles of at least 45 degrees, and center islands to prevent drivers from taking a straight "racing line" through the feature







Federal High Administrat



1099 14th Street, NV West Washington, 20005-3538 L Phone: 202-289 Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE | RAISED INTERS CLOSURE | NEIGHI TRAFFIC CIRCLE | CHOKER | CENTEI NARROWIN




5. Transoft

leading **CAD software** for transportation engineers







Potential Impacts:

- no effect on access
- limited data available on their effect on speed, volume, and collisions
- street sweeping may need to be done manually
- can impact parking and driveway access
- · provides opportunity for landscaping

Emergency Response Issues:


- limited data available on their effect on delay to emergency response
- emergency response typically prefer two-lane chicanes to speed humps

Typical Cost:

• reported costs range between \$5,000 and \$15,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org





Traffic Calming Measures - Choker

BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT

- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Description:

- curb extensions at midblock or intersection corners that narrow a street by extending the sidewalk or widening the planting strip
- can leave the cross section with two narrow lanes or with a single lane
- at midblock, sometimes called parallel chokers, angled chokers, twisted chokers, angle points, pinch points, or midblock narrowings
- at intersections, sometimes called neckdowns, bulbouts, knuckles, or corner bulges
- if marked as a crosswalk, they are also called safe crosses





Transoft

leading **CAD** software for transportation engineers

Applications:

- local and collector streets
- pedestrian crossings
- main roads through small communities
- work well with speed humps, speed tables, raised intersections, textured crosswalks, curb radius reductions, and raised median islands





Federal High Administrat



1099 14th Street, NV West Washington, 20005-3438 L Phone: 202-289 Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE I RAISED INTERS CLOSURE | NEIGHI TRAFFIC CIRCLE | CHOKER | CENTEL NARROWIN








Design/Installation Issues:

- · some applications use an island which allows drainage and bicyclists to continue between the choker and the original curb
- typically designed to narrow road to 20 feet for two-way traffic; typically avoid the use



- of widths between 13 and 17 feet
- adequate drainage is a key consideration
- provides opportunity for landscaping
- vertical delineators, bollards or object markers are often used to make visible to snowplow operators

Potential Impacts:

- · can impact parking and driveway access
- reduces pedestrian crossing width and increases visibility of pedestrian
- speeds have typically been reduced on average by 4 percent for twolane chokers and 14 percent for one lane chokers
- minor decrease in traffic for two-lane and 20 percent reduction for onelane chokers
- collision data not available
- bicyclists prefer not to have the travelway narrowed into path of motor vehicles

Emergency Response Issues:

 preferred by many fire department/emergency response agencies to most other traffic calming measures

Other/Special Considerations:

• one-lane chokers rely on regulatory signs and driver courtesy to work

Typical Cost:

approximately \$7,000 to \$10,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org





BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT DIRECTORIES MEETINGS

Traffic Calming Measures - Speed Hump


- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Description:

- rounded raised areas of pavement typically 12 to 14 feet in length
- often placed in a series (typically spaced 300 to 600 feet apart)
- · sometimes called road humps or undulations

Applications:

- residential streets
- not typically used on major roads, bus routes, or primary emergency response routes
- midblock placement, not at an intersection
- · not on grades greater than 8 percent
- work well with curb extensions



Design/Installation Issues:

- typically 12 to 14 feet in length; other lengths (10, 22, and 30 feet) reported in practice in U.S.
- speed hump shapes include parabolic, circular, and sinusoidal
- hump heights range between 3 and 4 inches with trend toward 3 - 3 ½ inches maximum
- difficult to construct precisely; may need to specify a construction tolerance (e.g. ± 1/8 inch) on height
- often have signage (advance warning sign before first hump in series and warning





Federal High Administrat



1099 14th Street, NW West Washington, 20005-3538 L Phone: 202-289-Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE | RAISED INTERSI CLOSURE | NEIGHI TRAFFIC CIRCLE | CHOKER | CENTEI NARROWIN




Transoft

leading CAD software for transportation

engineers







- sign or object marker at hump)
- typically have pavement marking (zigzag, shark's tooth, chevron, zebra)
- taper edge near curb to allow gap for drainage
- some have speed advisories
- bicyclists prefer that it not cover or cross a bike lane

Potential Impacts:

- · no effect on non-emergency access
- speeds determined by height and spacing; speeds between humps have been observed to be reduced between 20 and 25 percent on average
- based on a limited sample of sites, typical crossing speeds (85th percentile) of 19 mph have been measured for 3½ inch high, 12 foot humps and of 21 mph for 3 inch high, 14 foot humps; speeds have been observed to rise to 27 mph within 200 feet downstream
- speeds typically increase approximately 0.5 mph midway between humps for each 100 feet of separation
- studies indicate that traffic volumes have been reduced on average by 18 percent depending on alternative routes available
- studies indicate that collisions have been reduced on average by 13 percent on treated streets (not adjusted for traffic diversion)
- most communities limit height to 3-3½ inches, partly because of harsh ride over 4-inch high humps
- possible increase in traffic noise from braking and acceleration of vehicles, particularly buses and trucks

Emergency Response Issues:


- Concern over jarring of emergency rescue vehicles
- Approximate delay of between 3 and 5 seconds per hump for fire trucks and up to 10 seconds for ambulance with patient

Typical Cost:

Approximately \$2,000 (1997 dollars)

For additional detail, refer to ITE's Recommended Practice entitled *Guidelines* for the Design and Application of Speed Humps. Visit the ITE Bookstore for more information about this publication.

Institute of Transportation Engineers





EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT

- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Description:


 long raised speed humps with a flat section in the middle and ramps on the ends; sometimes constructed with brick or other textured materials on the flat section

Traffic Calming Measures - Speed Table

sometimes called flat top speed humps, trapezoidal humps, speed platforms, raised crosswalks, or raised crossings

Applications:

- local and collector streets
- main roads through small communities
- typically long enough for the entire wheelbase of a passenger car to rest on top
- work well in combination with textured crosswalks, curb extensions, and curb radius reductions
- can include a crosswalk









Federal High Administrat



1099 14th Street, NV West Washington, 20005-3538 L Phone: 202-289 Fax: 202-289-Send commen website@ite.

Design/Installation Issues:

- · typically 22 feet in the direction of travel with 6 foot ramps on each end and a 10 foot flat section in the middle; other lengths (32 and 48 feet) reported in U.S. practice
- most common height is between 3 and 4 inches (and reported as high as 6 inches)

SPEED HUMP | SPE | RAISED INTERS CLOSURE | NEIGHE TRAFFIC CIRCLE | 1 CHOKER | CENTE NARROWIN
















- ramps are typically 6 feet long (reported up to 10 feet long) and are either parabolic or linear
- careful design is needed for drainage

Potential Impacts:

- no effect on access
- speeds are reduced, but usually to a higher crossing speed than at speed humps (typically between 25 and 27 miles per hour)
- traffic volumes have been reduced on average by 12 percent depending on alternative routes available
- collisions have been reduced on average by 45 percent on treated streets (not adjusted for traffic diversion)
- reported to increase pedestrian visibility and likelihood that driver yields to pedestrian

Emergency Response Issues:


- typically preferred by fire departments over 12 to 14-foot speed humps
- generally less than 3 seconds of delay per hump for fire trucks

Typical Cost:

 approximately \$2,500 (in 1997 dollars) for asphalt tables; higher for brickwork, stamped asphalt, concrete ramps and other enhancements sometimes used at pedestrian crossings

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org





BOOKSTORE EMPLOYMENT CENTER TECHNICAL INFORMATION PROFESSIONAL DEVELOPMENT DIRECTORIES MEETINGS

Traffic Calming Measures - Raised Intersection


- > HOME
- > JOIN ITE TODAY!
- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Description:

- flat raised areas covering entire intersections, with ramps on all approaches and often with brick or other textured materials on the flat section and ramps
- sometimes called raised junctions, intersection humps, or plateaus

Applications:

- work well with curb extensions and textured crosswalks
- often part of an area wide traffic calming scheme involving both intersecting streets
- in densely developed urban areas where loss of parking would be unacceptable







Administrat



1099 14th Street, NV West Washington, 20005-3438 L Phone: 202-289-Fax: 202-289-Send commen website@ite.

SPEED HUMP | SPE | RAISED INTERSI | CLOSURE | NEIGHE | TRAFFIC CIRCLE | I | CHOKER | CENTEI | NARROWIN

Design/Installation Issues:

- · typically rise to sidewalk level
- may require bollards to define edge of roadway
- Canadian installations typically have gentle 1:40 slopes on ramps
- storm drainage modifications are necessary



leading
CAD software
for
transportation
engineers














Potential Impacts:

- reduction in through movement speeds at intersection
- reduction in midblock speeds typically less than 10 percent
- · no effect on access
- make entire intersections more pedestrian-friendly
- · no data available on volume or safety impacts

Emergency Response Issues:


• slows emergency vehicles to approximately 15 miles per hour

Typical Cost:

• reported costs range between \$15,000 and \$50,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org



A Community of Transportation Professionals
Your source for expertise, knowledge and ideas

BOOKSTORE

EMPLOYMENT CENTER

TECHNICAL INFORMATION

PROFESSIONAL DEVELOPMENT

DIRECTORIES

MEETINGS

SEARCH ITE

500,001

> HOME > JOIN ITE TODAY!

- > ABOUT ITE
- > ITE COUNCILS
- > MEMBERS ONLY
- > MARKETING
- > LOGIN
- > LOGOUT
- > PAY DUES
- > CHECKOUT

Description:


 raised islands located along the centerline of a street that narrow the travel lanes at that location


Traffic Calming Measures - Center Island Narrowing

• sometimes called midblock medians, median slow points, or median chokers

Aplications:

- · are often nicely landscaped to provide visual amenity and neighborhood identity
- can help pedestrianize streets by providing a mid-point refuge for pedestrians crossings
- sometimes used on wide streets to narrow travel lanes
- · work well when combined with crosswalks










1099 14th Street, NW Suite 300 West Washington, DC 20005-3438 USA Phone: 202-289-0222 Fax: 202-289-7722







Potential Impacts:

- may reduce parking and driveway access
- reduces pedestrian crossing width
- may visually enhance the street through landscaping but may also limit visibility of pedestrian crossings
- bicyclists prefer not to have the travel way narrowed into path of motor vehicles
- collision, speed and volume data are not available

Send comments to: website@ite.org

SPEED HUMP | SPEED TABLE |
RAISED INTERSECTION | CLOSURE |
NEIGHBORHOOD TRAFFIC CIRCLE |
CHICANE | CHOKER | CENTER ISLAND
NARROWING

Emergency Response Issues:

 preferred by fire department/emergency response agencies to most other traffic calming measures

Typical Cost:

reported costs range between \$5,000 and \$15,000 (1997 dollars)

Institute of Transportation Engineers

1099 14th Street, NW, Suite 300 West | Washington, DC 20005-3438 USA Telephone: +1 202-289-0222 | Fax: +1 202-289-7722 ite_staff@ite.org